Ealing St Peter:

REPAIRS TO THE WEST ELEVATION



PROGRESS PHOTOGRAPHS

Taken March-October 2017



Introduction

This project for the west elevation window and stonework represents a continuation of the work that we are completed to the north elevation in 2012 and to the South elevation in 2014. The works in the current project are more or less as anticipated and specified, but with some variation in the type and extent of the stone works necessary. The scaffolding is now erected and the windows have been removed for re-leading to the stained glass studios. Stone repairs and re-pointing are proceeding.



Figure 1 Typical view of tracery prior to removal showing distortion of leading



Figure 2 Typical view of tracery with temporary glazing



Figure 3 Typical views of ferementa showing that they are in perfect condition



Figure 4 re-pointing to gable




Figure 5 view showing apex of hood moulding cut out ready for replacement



Figure 6 view showing view of completed phoenix



Figure 7 view showing view of new gable coping






Figure 8 internal and external details of completed tracery glazing




Figure 9 internal and external details of glazing






Figure 10 internal and external views of completed window.